

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2018 Levee Inspection Results

Reclamation District No. 0817 Carlin

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection
Reports may effect overall annual rating.

† SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2018 Levee Inspection Results

Reclamation District No. 0817 Carlin

Waterway			Bank	Unit Miles
Unit No. 01 South Dry Creek			Left	3.81
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/18/2018 - 4/18/2018			
DWR Inspector	Sterling York			
Accompanied By	Joe Conant RD 817			
	Tom Engler RD 2103			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training				
DWR ID	DWR_RD0817_01_f_2014_5				
Comment Code					
Inspector Comment					
LMA regularly attends flood fight training put on by RD784 and DWR .					

No Photos

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals				
DWR ID	DWR_RD0817_01_s_2013_9				
Comment Code					
Inspector Comment					
The manuals are located at Tom Englers office and at Joe Conant's office.					

No Photos

LM Start		Rating **	A	Issue No.	10
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment				
DWR ID	DWR_RD0817_01_s_2013_10				
Comment Code					
Inspector Comment					
LMA stated that they have approx. 2500 sandbags and related flood fight material located in a mini storage in downtown Wheatland.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	0.00	Rating **	A	Issue No.	26
LM End	3.81	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.984668 °	39.019765 °
				-121.506110 °	-121.454085 °
DWR ID	DWR_RD0817_01_s_2018_26				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation is maintained, Spring 2018.					

Photo 1 of 1 : SP_2018_RD0817_12_26_20180501_00018.jpg



View looking downstream landside of the maintained annual vegetation, Spring 2018.

LM Start	0.00	Rating **	A	Issue No.	27
LM End	3.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.984668 °	39.019765 °
				-121.506110 °	-121.454085 °
DWR ID	DWR_RD0817_01_s_2018_27				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation is maintained, Spring 2018.					

Photo 1 of 1 : SP_2018_RD0817_12_27_20180501_00019.jpg



View looking downstream waterside of the maintained annual vegetation, Spring 2018.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	0.29	Rating **	M	Issue No.	28
LM End	0.29	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.987813 °	38.987813 °
				-121.502963 °	-121.502963 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:42685 DS_ID:18985 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Recommend having owner clear vegetation along slopes. FIELD_STRUCT_DESC: 48-inch corrugated metal gravity drainage pipe through the levee, 23.3 feet below the crown. Flap gate on the waterside (WS) end. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 0.28)]. FS Date: 4/16/2013					

Photo 1 of 3 : UCIP_SP_2018_42685_19865.jpg



WS- pipe, flap gate in dense vegetation on berm

LM Start	0.29	Rating **	M	Issue No.	28 (cont)
LM End	0.29	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_SP_2018_42685_19864.jpg



WS- CM pipe and flap gate

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	0.29	Rating **	M	Issue No.	28 (cont)	
LM End	0.29	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.987813 °	38.987813 °	
				-121.502963 °	-121.502963 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:42685 DS_ID:18985 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Recommend having owner clear vegetation along slopes. FIELD_STRUCT_DESC: 48-inch corrugated metal gravity drainage pipe through the levee, 23.3 feet below the crown. Flap gate on the waterside (WS) end. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 0.28)]. FS Date: 4/16/2013						

Photo 3 of 3 : UCIP_SP_2018_42685_19863.jpg



WS- dense vegetation on WS of the levee

LM Start	0.55	Rating **	U	Issue No.	29	
LM End	0.55	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.989890 °	38.989890 °	
				-121.498850 °	-121.498850 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:41299						
DS_ID:18999						
EP_NO: N/A						
Repair Type: Urgent						
Crossing Status: Not Found						
UCIP Comments: No markers visible. Need to contact owner to determine status of crossing. If crossing is still active owner will need to comply with Title 23.						
FIELD_STRUCT_DESC: 8-5/8 pipe through levee, 3 feet below the crown. O&M Manual Sac 146, November 1962.						
FS Date: 4/16/2013						

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	0.56	Rating **	M	Issue No.	30
LM End	0.56	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.989990 °	38.989990 °
				-121.498710 °	-121.498710 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41411 DS_ID:19000 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Not Found UCIP Comments: No markers were found. Dense vegetation limits inspector's visibility along waterward and landwar slopes. FIELD_STRUCT_DESC: 16-inch gas line through levee, 2.9 feet below the crown. O&M Manual Sac 146, November 1962. FS Date: 4/16/2013					

No Photos

LM Start	0.63	Rating **	U	Issue No.	31
LM End	0.63	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.990650 °	38.990650 °
				-121.497720 °	-121.497720 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41412 DS_ID:19001 EP_NO: N/A Repair Type: Urgent Crossing Status: Not Found UCIP Comments: No markers visible. Dense vegetation present on both sides of the levee slopes. Need to contact owner to determine status of crossing. If crossing is still active owner will need to comply with Title 23 and contact Central Valley Flood Protection Board (CVFPB). FIELD_STRUCT_DESC: 16-inch gas line through levee, 3 feet below the crown. O&M Manual Sac 146, November 1962. FS Date: 4/16/2013					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	0.83	Rating **	M	Issue No.	32	
LM End	0.83	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.992540 °	38.992540 °	
				-121.494920 °	-121.494920 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:41321						
DS_ID:19002						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Not Found						
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward and landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances.						
FIELD_STRUCT_DESC: 36-inch pipe through levee. Flap gate on waterside. O&M Manual Sac 146, November 1962.						
FS Date: 4/16/2013						

No Photos

LM Start	1.04	Rating **	M	Issue No.	33	
LM End	1.04	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.994640 °	38.994640 °	
				-121.492120 °	-121.492120 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:41322						
DS_ID:18986						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Not Found						
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward and landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances.						
FIELD_STRUCT_DESC: *REMOVED* 18-inch corrugated metal gravity drainage pipe through the levee, 13 feet below the crown. Slide gate on the waterside (WS) end. (18-inch pipe and appurtenances removed in 1989). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 1.04)].						
FS Date: 4/16/2013						

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	1.13	Rating **	M	Issue No.	34	
LM End	1.13	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.995667 °	38.995667 °	
				-121.490981 °	-121.490981 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:44084 DS_ID:25088 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No permit identified for this crossing. FIELD_STRUCT_DESC: *DUPLICATE--DELETE ENTRY* 4-inch steel telephone conduit through the levee, 4 feet below the crown. FS Date: 3/19/2015						

Photo 1 of 2 : UCIP_SP_2018_44084_73565.jpg



Communication conduit visible on upstream side of bridge.

LM Start	1.13	Rating **	M	Issue No.	34 (cont)
LM End	1.13	Issue Type +	En	Location *	

Photo 2 of 2 : UCIP_SP_2018_44084_73564.jpg



Fiberoptic line markers along roadway to south of bridge.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	1.14	Rating **	M	Issue No.	35
LM End	1.14	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		38.995739 °	38.995739 °	
			-121.490894 °	-121.490894 °	
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:44085 DS_ID:18997 EP_NO: 1454 Repair Type: Non-Urgent Crossing Status: Not Found UCIP Comments: Pipe Abandoned and should be done so properly. FIELD_STRUCT_DESC: *ABANDONED* 24-inch corrugated metal gravity drainage pipe through the levee, 17 feet below the crown. Slide gate on the waterside (WS) slope. 6-foot by 6-foot by 8-inch concrete cutoff wall below each shoulder. (24-inch corrugated metal gravity drainage pipe authorized under Permit No. 1454, 1949 - Charles Sing). Pipe abandoned in place and covered with soil according to Reclamation District No. 817. FS Date: 3/26/2015					

No Photos

LM Start	1.34	Rating **	M	Issue No.	36
LM End	1.34	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.997961 °	38.997961 °	
			-121.488455 °	-121.488455 °	
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41153 DS_ID:18987 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Damaged slide gate on WS of the levee. Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to contact CVFPB to comply with Title 23. Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Recommend having owner clear vegetation along slopes. FIELD_STRUCT_DESC: *ABANDONED* 18-inch corrugated metal gravity drainage pipe through the levee, 14.9 feet below the crown. Slide gate on the waterside (WS) end. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 1.34)]. FS Date: 4/16/2013					

Photo 1 of 3 : UCIP_SP_2018_41153_19882.jpg



WS- overview of WS area

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	1.34	Rating **	M	Issue No.	36 (cont)	
LM End	1.34	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.997961 °	38.997961 °	
				-121.488455 °	-121.488455 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:41153						
DS_ID:18987						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Damaged slide gate on WS of the levee. Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to contact CVFPB to comply with Title 23. Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Recommend having owner clear vegetation along slopes.						
FIELD_STRUCT_DESC: *ABANDONED* 18-inch corrugated metal gravity drainage pipe through the levee, 14.9 feet below the crown. Slide gate on the waterside (WS) end. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 1.34)].						
FS Date: 4/16/2013						

Photo 2 of 3 : UCIP_SP_2018_41153_19881.jpg



WS- closer look at damaged slide gate on WS

LM Start	1.34	Rating **	M	Issue No.	36 (cont)
LM End	1.34	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2018_41153_19884.jpg



LS- CMP on toe of the levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	1.62	Rating **	M	Issue No.	37	
LM End	1.62	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.001340 °	39.001340 °	
				-121.485740 °	-121.485740 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:41157						
DS_ID:18988						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: A burried slide gate on WS of the levee. Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to contact CVFPB to comply with Title 23. Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Recommend having owner clear vegetation along slopes.						
FIELD_STRUCT_DESC: *ABANDONED* 18-inch corrugated metal gravity drainage pipe through the levee, 13.8 feet below the crown. Slide gate on the waterside (WS) end. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 1.62)].						
FS Date: 4/16/2013						

LM Start	1.62	Rating **	M	Issue No.	37 (cont)
LM End	1.62	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2018_41157_19892.jpg



WS- overview of WS berm

Photo 2 of 3 : UCIP_SP_2018_41157_19891.jpg



WS- slide gate

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	1.62	Rating **	M	Issue No.	37 (cont)	
LM End	1.62	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.001340 °	39.001340 °	
				-121.485740 °	-121.485740 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:41157						
DS_ID:18988						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: A burried slide gate on WS of the levee. Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to contact CVFPB to comply with Title 23. Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Recommend having owner clear vegetation along slopes.						
FIELD_STRUCT_DESC: *ABANDONED* 18-inch corrugated metal gravity drainage pipe through the levee, 13.8 feet below the crown. Slide gate on the waterside (WS) end. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 1.62)].						
FS Date: 4/16/2013						

Photo 3 of 3 : UCIP_SP_2018_41157_19890.jpg



WS- buried slide gate

LM Start	1.74	Rating **	M	Issue No.	8
LM End	3.81	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.002941 °	39.019763 °
				-121.484856 °	-121.454151 °
DWR ID	DWR_RD0817_01_s_2013_8				
Comment Code					
FE : Fence					
Inspector Comment					
Wire fence at L/S levee toe.					

Photo 1 of 2 : SP_2018_RD0817_12_8_20180302_00001.jpg



Wire fence still exist at the landside levee toe. Fall 2017.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	1.74	Rating **	M	Issue No.	8 (cont)	
LM End	3.81	Issue Type +	En	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			39.002941 °		39.019763 °
				-121.484856 °		-121.454151 °
DWR ID	DWR_RD0817_01_s_2013_8					
Comment Code						
FE : Fence						
Inspector Comment						
Wire fence at L/S levee toe.						

Photo 2 of 2 : SP_2018_RD0817_12_8_20180302_00002.jpg



Wire fence at L/S levee toe. Fall 2016.

LM Start	1.86	Rating **	M	Issue No.	38
LM End	1.86	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.004520 °	39.004520 °
				-121.483960 °	-121.483960 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41323					
DS_ID:19003					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Not Found					
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward and landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances.					
FIELD_STRUCT_DESC: 12-inch pipe through levee. Vertical Pump on WS. 3.1 feet below the crown. O&M Manual Sac 146, November 1962.					
FS Date: 4/16/2013					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	2.06	Rating **	M	Issue No.	39	
LM End	2.06	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.006760 °	39.006760 °	
				-121.481670 °	-121.481670 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:41312 DS_ID:19004 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Not Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward and landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. FIELD_STRUCT_DESC: 18-inch pipe through the levee, 11.5 feet below the crown. O&M Manual Sac 146, November 1962. FS Date: 4/16/2013						

No Photos

LM Start	2.29	Rating **	M	Issue No.	40
LM End	2.29	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.008353 °	39.008353 °
				-121.477963 °	-121.477963 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41156 DS_ID:18989 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: A burried slide gate found on WS. Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to contact CVFPB to comply with Title 23. Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Recommend having owner clear vegetation along slopes. FIELD_STRUCT_DESC: *ABANDONED* 18-inch corrugated metal gravity drainage pipe through levee, 11.7 feet below the crown. Slide gate on the waterside (WS) end. (Removal of 18-inch pipe and appurtenances authorized under Permit No. 16193, 1994 - Reclamation District No. 817. Slide gate still remains on the WS toe). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 2.29)]. FS Date: 4/16/2013					

Photo 1 of 1 : UCIP_SP_2018_41156_19895.jpg



WS- slide gate on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	2.30	Rating **	M	Issue No.	41
LM End	2.30	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.008425 °	39.008425 °	
			-121.477775 °	-121.477775 °	
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41318 DS_ID:18993 EP_NO: 16193 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward and landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. FIELD_STRUCT_DESC: Remove (1 of 3 locations) abandoned 18-inch diameter pipeline from the left bank levee of Dry Creek. (App. No. 16193) FS Date: 4/16/2013					

No Photos

LM Start	2.39	Rating **	M	Issue No.	42
LM End	2.39	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.008980 °	39.008980 °	
			-121.476260 °	-121.476260 °	
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41324 DS_ID:19005 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Not Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward and landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. FIELD_STRUCT_DESC: 10-inch pipe through levee. Vertical Pump on WS. 2.8 feet below the crown. O&M Manual Sac 146, November 1962. FS Date: 4/16/2013					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	2.64	Rating **	M	Issue No.	43
LM End	2.64	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.010523 °	39.010523 °	
			-121.472070 °	-121.472070 °	
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41319 DS_ID:18994 EP_NO: 16193 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward and landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. FIELD_STRUCT_DESC: Remove (1 of 3 locations) abandoned 18-inch diameter pipeline from the left bank levee of Dry Creek. (App. No. 16193) FS Date: 4/16/2013					

No Photos

LM Start	2.65	Rating **	M	Issue No.	44
LM End	2.65	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.010584 °	39.010584 °	
			-121.471902 °	-121.471902 °	
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:47111 DS_ID:18990 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Not Found UCIP Comments: Pipe Abandoned in place and should be done so properly. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward and landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. FIELD_STRUCT_DESC: *REMOVED* 18-inch corrugated metal gravity drainage pipe through the levee, 10.5 feet below the crown. Slide gate on the waterside (WS) end. (Removal of 18-inch pipe and appurtenances authorized under Permit No. 16193, 1994 - Reclamation District No. 817). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 2.65)]. FS Date: 3/26/2015					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	2.68	Rating **	M	Issue No.	45
LM End	2.68	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.010770 °	39.010770 °	
			-121.471400 °	-121.471400 °	
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41325 DS_ID:19006 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Not Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward and landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. FIELD_STRUCT_DESC: 8-inch pipe through the levee. Pump on LS. 3.1 feet below the crown. O&M Manual Sac 146, November 1962. FS Date: 4/16/2013					

No Photos

LM Start	2.96	Rating **	M	Issue No.	46
LM End	2.96	Issue Type +	En	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		39.012500 °	39.012500 °	
			-121.466700 °	-121.466700 °	
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41320 DS_ID:18995 EP_NO: 16193 Repair Type: Non-Urgent Crossing Status: Not Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward and landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. FIELD_STRUCT_DESC: Remove (1 of 3 locations) abandoned 18-inch diameter pipeline from the left bank levee of Dry Creek. (App. No. 16193) FS Date: 4/16/2013					

No Photos

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	2.96	Rating **	M	Issue No.	47
LM End	2.96	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.012552 °	39.012552 °
				-121.466538 °	-121.466538 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:43946 DS_ID:18992 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Flapgate in closed position, but blocked from operation on WS toe. Pipe appears abandoned and should be verified as having been done so properly. FIELD_STRUCT_DESC: 36-inch corrugated metal gravity drainage pipe through the levee, 13.7 feet below the crown. Slide gate on the waterside (WS) end. Flap gate on the WS end. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 2.97)]. FS Date: 3/26/2015					

LM Start	2.96	Rating **	M	Issue No.	47 (cont)
LM End	2.96	Issue Type +	Ma	Location *	

Pipe and flapgate visible on WS toe.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable AWW : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 South Dry Creek	Left	3.81	04/18/2018 04/18/2018	Sterling York

LM Start	2.96	Rating **	M	Issue No.	47 (cont)	
LM End	2.96	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.012552 °	39.012552 °	
				-121.466538 °	-121.466538 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:43946 DS_ID:18992 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Flapgate in closed position, but blocked from operation on WS toe. Pipe appears abandoned and should be verified as having been done so properly. FIELD_STRUCT_DESC: 36-inch corrugated metal gravity drainage pipe through the levee, 13.7 feet below the crown. Slide gate on the waterside (WS) end. Flap gate on the WS end. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 2.97)]. FS Date: 3/26/2015						

Photo 3 of 3 : UCIP_SP_2018_43946_73420.jpg



LS of pipe buried but alignment would place LS outlet just left of telephone pole on LS toe.

LM Start	3.69	Rating **	M	Issue No.	48
LM End	3.69	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.018890 °	39.018890 °
				-121.455920 °	-121.455920 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41316					
DS_ID:19007					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Not Found					
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the waterward and landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances.					
FIELD_STRUCT_DESC: 18-inch pipe through levee. Flap gate on WS. 12 feet below the crown. O&M Manual Sac 146, November 1962.					
FS Date: 4/16/2013					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2018 Levee Inspection Results

Reclamation District No. 0817 Carlin

Waterway			Bank	Unit Miles
Unit No. 02 Bear River			Right	3.86
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/18/2018 - 4/18/2018			
DWR Inspector	Sterling York			
Accompanied By	Joe Conant RD 817			
	Tom Engler RD 2103			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	0.00	Rating **	A	Issue No.	10
LM End	3.85	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.984646 °	38.993339 °
				-121.506111 °	-121.437456 °
DWR ID	DWR_RD0817_02_s_2018_10				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation is maintained, Spring 2018.					

Photo 1 of 1 : SP_2018_RD0817_13_10_20180501_00026.jpg



View looking upstream landside of the maintained annual vegetation, Spring 2018.

LM Start	0.00	Rating **	A	Issue No.	16
LM End	3.85	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.984646 °	38.993339 °
				-121.506111 °	-121.437456 °
DWR ID	DWR_RD0817_02_s_2018_16				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation is maintained, Spring 2018.					

Photo 1 of 1 : SP_2018_RD0817_13_16_20180501_00028.jpg



View looking upstream waterside of the maintained annual vegetation, Spring 2018.

LM Start	0.32	Rating **	C	Issue No.	20
LM End	0.49	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.984425 °	38.984727 °
				-121.500596 °	-121.497388 °
DWR ID	DWR_RD0817_02_f_2017_20				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Wild Rose Bushes have been removed from Levee toe and slope, Spring 2018.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	0.99	Rating **	M	Issue No.	23
LM End	0.99	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.985571 °	38.985571 °
				-121.488209 °	-121.488209 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:44064 DS_ID:19008 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Pipe appears abandoned and if so should be done so properly. Concrete standpipe filled with soil. FIELD_STRUCT_DESC: *ABANDONED* 10-inch gravity drainage pipe of an unknown material through the levee, 13.5 feet below the crown. No control valves. Hole in pipe at the landside (LS) toe. 36-inch concrete riser at the LS toe. Concrete standpipe at the LS toe. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 1.01), 12-inch pipe referenced]. FS Date: 4/1/2015					

Photo 1 of 3 : UCIP_SP_2018_44064_73542.jpg



Concrete standpipe visible on lower slope of LS toe.

LM Start	0.99	Rating **	M	Issue No.	23 (cont)
LM End	0.99	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_44064_73541.jpg



Concrete standpipe visible on lower slope of LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	0.99	Rating **	M	Issue No.	23 (cont)	
LM End	0.99	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.985571 °	38.985571 °	
				-121.488209 °	-121.488209 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:44064						
DS_ID:19008						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Indicator Found						
UCIP Comments: Pipe appears abandoned and if so should be done so properly. Concrete standpipe filled with soil.						
FIELD_STRUCT_DESC: *ABANDONED* 10-inch gravity drainage pipe of an unknown material through the levee, 13.5 feet below the crown.						
No control valves. Hole in pipe at the landside (LS) toe. 36-inch concrete riser at the LS toe. Concrete standpipe at the LS toe.						
[Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 1.01), 12-inch pipe referenced].						
FS Date: 4/1/2015						

Photo 3 of 3 : UCIP_SP_2018_44064_73540.jpg



Concrete standpipe visible on lower slope of LS toe.

LM Start	1.29	Rating **	U	Issue No.	24	
LM End	1.29	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.986150 °	38.986150 °	
				-121.482770 °	-121.482770 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:41302 DS_ID:19013 EP_NO: N/A Repair Type: Urgent Crossing Status: Not Found UCIP Comments: No markers visible. Need to contact owner to determine status of crossing. If crossing is still active owner will need to comply with Title 23 and contact Central Valley Flood Protection Board (CVFPB). FIELD_STRUCT_DESC: 16-inch gas line through levee, 3 feet below the crown. O&M Manual Sac 146, November 1962. FS Date: 4/17/2013						

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	1.47	Rating **	M	Issue No.	15
LM End	1.47	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.986563 °	38.986563 °
				-121.479509 °	-121.479509 °
DWR ID	DWR_RD0817_02_f_2016_15				
Comment Code					
Inspector Comment					
Sink hole were old stump was needs to be backfilled and compacted. Spring 2018.					

Photo 1 of 1 : SP_2018_RD0817_13_15_20180302_00011.jpg



View of a sink hole were old stump was. This needs to be backfilled and compacted. Fall 2016.

LM Start	1.54	Rating **	M	Issue No.	11
LM End	1.54	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.986877 °	38.986877 °
				-121.478175 °	-121.478175 °
DWR ID	DWR_RD0817_02_s_2017_11				
Comment Code					
PR : Prunings					
Inspector Comment					
Have pruning's removed from toe area, Spring 2018.					

Photo 1 of 1 : SP_2018_RD0817_13_11_20180302_00003.jpg



View of pruning's on the landside levee toe, Fall 2017.

LM Start	1.76	Rating **	M	Issue No.	2
LM End	1.76	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.987851 °	38.987851 °
				-121.474383 °	-121.474383 °
DWR ID	DWR_RD0817_02_f_2013_2				
Comment Code					
V6 : Landscaping					
Inspector Comment					
The homeowners landscape vegetation is creeping up the landside levee slope.					

Photo 1 of 1 : SP_2018_RD0817_13_2_20180302_00001.jpg



View of the homeowners landscape vegetation creeping up the landside levee slope, looking upstream. Fall 2016.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	1.77	Rating **	U	Issue No.	25
LM End	1.77	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.987920 °	38.987920 °
				-121.474080 °	-121.474080 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41304 DS_ID:19015 EP_NO: N/A Repair Type: Urgent Crossing Status: Not Found UCIP Comments: No markers visible. Need to contact owner to determine status of crossing. If crossing is still active owner will need to comply with Title 23 and contact Central Valley Flood Protection Board (CVFPB). FIELD_STRUCT_DESC: 8-5/8-inch gas line through the levee, 3 feet below the crown. O&M Manual Sac 146, November 1962. FS Date: 4/17/2013					

No Photos

LM Start	1.81	Rating **	M	Issue No.	12
LM End	1.85	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.988102 °	38.988285 °
				-121.473345 °	-121.472699 °
DWR ID	DWR_RD0817_02_s_2017_12				
Comment Code					
FW : Firewood					
Inspector Comment					
Large pile of firewood needs to be remove from levee toe, Spring 2018.					

Photo 1 of 1 : SP_2018_RD0817_13_12_20180302_00004.jpg



View of a large pile of firewood that is encroaching on the landside levee toe, Spring 2017 and still exist during Fall 2017 inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	1.89	Rating **	M	Issue No.	22
LM End	1.89	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.988461 °	38.988461 °
				-121.472105 °	-121.472105 °
DWR ID	DWR_RD0817_02_f_2017_22				
Comment Code					
PR : Prunings					
Inspector Comment					
Prunings need to be removed from levee toe.					

Photo 1 of 1 : SP_2018_RD0817_13_22_20180302_00013.jpg



View looking upstream landside of pruning's on the levee toe, Fall 2017.

LM Start	2.01	Rating **	M	Issue No.	3
LM End	2.01	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.989030 °	38.989030 °
				-121.469864 °	-121.469864 °
DWR ID	DWR_RD0817_02_s_2016_3				
Comment Code					
EQ : Equipment					
Inspector Comment					
Equipment encroaching onto the landside toe is still the same for Spring 2018 inspection.					

Photo 1 of 1 : SP_2018_RD0817_13_3_20180302_00002.jpg



Photo of equipment encroaching onto the landside toe. This is still the same for Fall 2016 inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	2.05	Rating **	M	Issue No.	26
LM End	2.05	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.989212 °	38.989212 °
				-121.469137 °	-121.469137 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46182 DS_ID:25095 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to determine permit for crossing. FIELD_STRUCT_DESC: 2-inch galvanized iron (GI) water line through the levee, at an unknown depth. Hose bib at the waterside (WS) toe. Possible connection at the building corner on the landside (LS). FS Date: 4/1/2015					

Photo 1 of 3 : UCIP_SP_2018_46182_74559.jpg



Pipe and hose bib visible in tall grass at WS toe.

LM Start	2.05	Rating **	M	Issue No.	26 (cont)
LM End	2.05	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_46182_74560.jpg



Possible source on LS at building corner.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	2.05	Rating **	M	Issue No.	26 (cont)
LM End	2.05	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.989212 °	38.989212 °
				-121.469137 °	-121.469137 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46182 DS_ID:25095 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to determine permit for crossing. FIELD_STRUCT_DESC: 2-inch galvanized iron (GI) water line through the levee, at an unknown depth. Hose bib at the waterside (WS) toe. Possible connection at the building corner on the landside (LS). FS Date: 4/1/2015					

Photo 3 of 3 : UCIP_SP_2018_46182_74561.jpg



Pipe and hose bib visible in tall grass at WS toe.

LM Start	2.08	Rating **	A/W	Issue No.	13	
LM End	3.18	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			38.989338 °	38.994124 °	
				-121.468640 °	-121.449448 °	
DWR ID	DWR_RD0817_02_f_2017_13					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:162						
Site Designation:DWR_RD0817_02_s_2012_10						
Repair Type: Stability						
Rating:Area of Concern						
Field Date:6/5/2017						
Notes: Stability issues are due to levee geometry. Narrow steep slopes.						

Photo 1 of 3 : LEVAL_SP_2018_162_287.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	2.08	Rating **	A/W	Issue No.	13 (cont)	
LM End	3.18	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			38.989338 °	38.994124 °	
				-121.468640 °	-121.449448 °	
DWR ID	DWR_RD0817_02_f_2017_13					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:162						
Site Designation:DWR_RD0817_02_s_2012_10						
Repair Type: Stability						
Rating:Area of Concern						
Field Date:6/5/2017						
Notes: Stability issues are due to levee geometry. Narrow steep slopes.						

LM Start	2.08	Rating **	A/W	Issue No.	13 (cont)
LM End	3.18	Issue Type +	Ma	Location *	

Photo 2 of 3 : LEVAL_SP_2018_162_288.jpg



Photo 3 of 3 : LEVAL_SP_2018_162_289.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	2.11	Rating **	M	Issue No.	27
LM End	2.11	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.989495°	38.989495°
				-121.468100°	-121.468100°
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:44105 DS_ID:19010 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe appears abandoned and should be done so properlyl. FIELD_STRUCT_DESC: *ABANDONED* 2-inch pipe of an unknown material or purpose through the levee, 1.5 feet below the crown. Concrete bulkhead on the landside (LS) slope. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 2.15), 1.25-inch pipe referenced]. FS Date: 4/1/2015					

Photo 1 of 3 : UCIP_SP_2018_44105_73586.jpg



Pipe visible on LS shoulder.

LM Start	2.11	Rating **	M	Issue No.	27 (cont)
LM End	2.11	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_44105_73585.jpg



WS slope. pipe not visible.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	2.11	Rating **	M	Issue No.	27 (cont)	
LM End	2.11	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.989495 °	38.989495 °	
				-121.468100 °	-121.468100 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:44105 DS_ID:19010 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe appears abandoned and should be done so properly. FIELD_STRUCT_DESC: *ABANDONED* 2-inch pipe of an unknown material or purpose through the levee, 1.5 feet below the crown. Concrete bulkhead on the landside (LS) slope. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 2.15), 1.25-inch pipe referenced]. FS Date: 4/1/2015						

Photo 3 of 3 : UCIP_SP_2018_44105_73584.jpg



Pipe and concrete headwall visible on LS shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	2.38	Rating **	M	Issue No.	28	
LM End	2.38	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.990705 °	38.990705 °	
				-121.463377 °	-121.463377 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:41160 DS_ID:19011 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Erosion present behind headwall. Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to contact CVFPB to comply with Title 23. Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Recommend having owner clear vegetation along slopes. FIELD_STRUCT_DESC: 24-inch irrigation pipe of an unknown material through the levee, 12 feet below the crown. Slide gate in a corrugated metal pipe (CMP) riser on the waterside (WS) slope. Abandoned pump and concrete riser on the bank. A tall CMP riser with an 8-inch siphon breaker pipe at the landside (LS) toe. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 2.41)]. FS Date: 4/17/2013						

LM Start	2.38	Rating **	M	Issue No.	28 (cont)
LM End	2.38	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_41160_19922.jpg



WS- CMP riser on levee slope.

Photo 2 of 3 : UCIP_SP_2018_41160_19921.jpg



WS- inside CMP riser with air vent and slide gate.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	2.38	Rating **	M	Issue No.	28 (cont)	
LM End	2.38	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.990705 °	38.990705 °	
				-121.463377 °	-121.463377 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:41160 DS_ID:19011 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Erosion present behind headwall. Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to contact CVFPB to comply with Title 23. Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Recommend having owner clear vegetation along slopes. FIELD_STRUCT_DESC: 24-inch irrigation pipe of an unknown material through the levee, 12 feet below the crown. Slide gate in a corrugated metal pipe (CMP) riser on the waterside (WS) slope. Abandoned pump and concrete riser on the bank. A tall CMP riser with an 8-inch siphon breaker pipe at the landside (LS) toe. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 146, November 1962, (HLM 2.41)]. FS Date: 4/17/2013						

Photo 3 of 3 : UCIP_SP_2018_41160_19920.jpg



WS- CMP riser with air vent and slide gate.

LM Start	2.72	Rating **	A/W	Issue No.	14
LM End	2.74	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.992170 °	38.992217 °
				-121.457332 °	-121.456967 °
DWR ID	DWR_RD0817_02_f_2017_14				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:161					
Site Designation:240-3					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:6/5/2017					
Notes: No issue found. Narrow levee with steep slopes. Did not investigate bench due to rattlesnake concerns. Possible alternate location at 38.993282; -121.451562.					

Photo 1 of 3 : LEVAL_SP_2018_161_1065.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	2.72	Rating **	A/W	Issue No.	14 (cont)
LM End	2.74	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.992170 °	38.992217 °
				-121.457332 °	-121.456967 °
DWR ID	DWR_RD0817_02_f_2017_14				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:161					
Site Designation:240-3					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:6/5/2017					
Notes: No issue found. Narrow levee with steep slopes. Did not investigate bench due to rattlesnake concerns. Possible alternate location at 38.993282; -121.451562.					

Photo 2 of 3 : LEVAL_SP_2018_161_283.jpg



Photo 3 of 3 : LEVAL_SP_2018_161_291.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Bear River	Right	3.86	04/18/2018 04/18/2018	Sterling York

LM Start	3.63	Rating **	A/W	Issue No.	17
LM End	3.63	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.992774 °	38.992774 °
				-121.441323 °	-121.441323 °
DWR ID	DWR_RD0817_02_f _ 2016_17				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2018 Levee Inspection Results

Reclamation District No. 0817 Carlin

Waterway			Bank	Unit Miles
Unit No. 03 South Dry Creek			Right	1.32
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/18/2018 - 4/18/2018			
DWR Inspector	Sterling York			
Accompanied By	Joe Conant RD 817			
	Tom Engler RD 2103			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	0.25	Rating **	M	Issue No.	11
LM End	1.56	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.987584 °	39.000521 °
				-121.506609 °	-121.490617 °
DWR ID	DWR_RD0817_03_s_2017_11				
Comment Code					
C3 : Add appropriate gravel or road base. Grade and compact.					
Inspector Comment					
More road base should be placed on the crown, Spring 2018.					

Photo 1 of 1 : SP_2018_RD0817_14_11_20180302_00003.jpg



View looking upstream of typical bare spots on the levee crown that need more aggregate base, Spring 2017.

LM Start	0.26	Rating **	A	Issue No.	13
LM End	1.27	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.987656 °	38.996874 °
				-121.506461 °	-121.491945 °
DWR ID	DWR_RD0817_03_s_2018_13				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation is maintained, Spring 2018.					

Photo 1 of 1 : SP_2018_RD0817_14_13_20180501_00029.jpg



View looking downstream waterside of the maintained annual vegetation, Spring 2018.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	0.26	Rating **	A	Issue No.	12
LM End	1.27	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.987656 °	38.996875 °
				-121.506461 °	-121.491944 °
DWR ID	DWR_RD0817_03_s_2018_12				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation is maintained, Spring 2018.					

Photo 1 of 1 : SP_2018_RD0817_14_12_20180501_00030.jpg



View looking downstream landside of the maintained annual vegetation, Spring 2018.

LM Start	0.27	Rating **	M	Issue No.	21
LM End	0.27	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.987762 °	38.987762 °
				-121.506271 °	-121.506271 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:50231 DS_ID:22949 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 06/30/2016 Vegetation has been cleared at outlet enough to allow the flapgate to open by half a foot. Recommend rechecking WS outlet prior to flood season to ensure no overgrowth. Dense vegetation at LS but pipe still functional. Crossing has been downgraded from Urgent to Non-Urgent. (K. Fazel - UCIP)02/27/2013 Flap gate partially blocked by vegetation at outlet. (G. Wylie - FPIIB) FIELD_STRUCT_DESC: 18-inch corrugated metal gravity drainage pipe through the levee, 19.5 feet below the crown. Flap gate and headwall on the waterside (WS) end, headwall not found in 2016. (Due to a recent change in the levee alignment, this pipe is no longer in RD0784, Unit 6. Nevertheless, this pipe's original references remain in the RD0784 Levee Log and O&M Manual). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 145.1, August 1955, (Station 21+35), As-Built Drawing No. 2-4-106, Sheet 2, (Station 21+35)]. FS Date: 6/30/2016 9:02:00 AM					

Photo 1 of 3 : UCIP_SP_2018_50231_54271.jpg



Pipe at LS toe

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

Reclamation District No. 0817 Carlin

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	0.27	Rating **	M	Issue No.	22
LM End	0.27	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.987762 °	38.987762 °
				-121.506283 °	-121.506283 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:42686 DS_ID:19025 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to contact CVFPB to comply with Title 23. Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Recommend having owner clear vegetation along slopes. FIELD_STRUCT_DESC: A 20-inch CM drainage pipe through levee. Flap Gate on WS levee toe. O&M Manual Sac 145, August 1955. FS Date: 4/17/2013					

Photo 1 of 3 : UCIP_SP_2018_42686_19927.jpg



LS- overview of CM drainage pipe on toe of the levee.

LM Start	0.27	Rating **	M	Issue No.	22 (cont)
LM End	0.27	Issue Type +	En	Location *	

Photo 2 of 3 : UCIP_SP_2018_42686_19926.jpg



LS- CM drainage pipe on toe of the levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	0.27	Rating **	M	Issue No.	22 (cont)	
LM End	0.27	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.987762 °	38.987762 °	
				-121.506283 °	-121.506283 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:42686 DS_ID:19025 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to contact CVFPB to comply with Title 23. Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Recommend having owner clear vegetation along slopes. FIELD_STRUCT_DESC: A 20-inch CM drainage pipe through levee. Flap Gate on WS levee toe. O&M Manual Sac 145, August 1955. FS Date: 4/17/2013						

Photo 3 of 3 : UCIP_SP_2018_42686_19928.jpg



WS- flap gate on CMP end on levee toe.

LM Start	0.32	Rating **	M	Issue No.	8
LM End	0.63	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.988147 °	38.990621 °
				-121.505500 °	-121.500680 °
DWR ID	DWR_RD0784_06_f_2012_8				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Dense berry bushes and other wild growth along slope, Spring 2018.					

Photo 1 of 1 : SP_2018_RD0817_14_8_20180501_00031.jpg



View of blackberry bushes that are taking over the landside slope looking upstream. Spring 2018.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	0.53	Rating **	M	Issue No.	4
LM End	0.63	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.989855 °	38.990621 °
				-121.502229 °	-121.500676 °
DWR ID	DWR_RD0817_03_s_2015_4				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
Trim tree limbs for access and visibility. Spring 2018.					

Photo 1 of 2 : SP_2018_RD0817_14_4_20180501_00032.jpg



View looking downstream of trees that need limbs to be trimmed for access and visibility, Spring 2018.

LM Start	0.53	Rating **	M	Issue No.	4 (cont)
LM End	0.63	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP_2018_RD0817_14_4_20180302_00001.jpg



View looking downstream of trees that need limbs to be trimmed for access and visibility, Fall 2017.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	0.53	Rating **	M	Issue No.	18
LM End	0.78	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.989855 °	38.991990 °
				-121.502228 °	-121.498536 °
DWR ID	DWR_RD0817_03_s_2017_18				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Black Berry bushes and other wild growth are taking over landside slope and need to be removed.					

Photo 1 of 1 : SP_2018_RD0817_14_18_20180302_00005.jpg



View looking downstream of Black Berry bushes, trees and other wild growth that are taking over the landside slope this remains the same for Fall 2017.

LM Start	0.54	Rating **	U	Issue No.	23
LM End	0.54	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.989915 °	38.989915 °
				-121.502113 °	-121.502113 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:50230 DS_ID:22950 EP_NO: N/A Repair Type: Urgent Crossing Status: Found UCIP Comments: 06/30/2016 Holes still present through pipe on corroded landside (LS) end. Pipe still half full of debris as visible thru LS end. Good candidate for removal via DWR's Deferred Maintenance Program. WS vegetation cleared in the immediate vicinity of flapgate. Potential for overgrowth at WS end nevertheless imminent. Note that this pipe does not cause LS nuisance flooding per Tom Engler of MBK. (K. Fazel - UCIP)03/25/2013 Pipe heavily corroded and failing at inlet an outlet. (G. Wylie - FPIIB) FIELD_STRUCT_DESC: 24-inch corrugated metal gravity drainage pipe through the levee, 20.5 feet below the crown. Flap gate and headwall on the waterside (WS) end. (Due to a recent change in the levee alignment, this pipe is no longer in RD0784, Unit 6. Nevertheless, this pipe's original references remain in the RD0784 Levee Log and O&M Manual). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 145.1, August 1955, (Station 35+57), As-Built Drawing No. 2-4-106, Sheet 4, (Station 35+57)]. FS Date: 6/30/2016 9:02:00 AM					

Photo 1 of 3 : UCIP_SP_2018_50230_53849.jpg



Pipe on LS toe corroded through.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

Reclamation District No. 0817 Carlin

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	0.55	Rating **	M	Issue No.	20
LM End	0.60	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.989976 °	38.990403 °
				-121.501970 °	-121.501110 °
DWR ID	DWR_RD0817_03_s_2017_20				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Trees and dense bushes need to be remove from levee slope.					

Photo 1 of 1 : SP_2018_RD0817_14_20_20180302_00007.jpg



View looking downstream of trees and bushes that block the view of the levee slope, Spring 2017 and remain the same for Fall 2017.

LM Start	0.68	Rating **	U	Issue No.	24
LM End	0.68	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.991062 °	38.991062 °
				-121.499886 °	-121.499886 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:50232 DS_ID:22951 EP_NO: N/A Repair Type: Urgent Crossing Status: Found UCIP Comments: 06/30/2016 Corrosion still present on WS end. Inlet box was replaced 5 years ago and appears to be functioning properly due to the presence of a screen that prevents debris blockage. Flap gate functions properly only sometimes. WS heavily vegetated. (K. Fazel - UCIP) 03/25/2013 Corrosion holes on WS toe and flap gate is blocked by debris. Flap gate broken. Inlet partially blocked at concrete inlet. (G. Wylie - FPIIB) FIELD_STRUCT_DESC: 24-inch corrugated metal gravity drainage pipe through the levee, 20 feet below the crown. Flap gate and headwall on the waterside (WS) end. 56-inch by 34-inch concrete inlet box on the landside (LS) toe. (Due to a recent change in the levee alignment, this pipe is no longer in RD0784, Unit 6. Nevertheless, this pipe's original references remain in the RD0784 Levee Log and O&M Manual). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 145.1, August 1955, (Station 43+17), As-Built Drawing No. 2-4-106, Sheet 4, (Station 43+17)]. FS Date: 6/30/2016 9:03:00 AM					

Photo 1 of 3 : UCIP_SP_2018_50232_53854.jpg



Pipe and flapgate at WS toe blocked by debris.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	0.68	Rating **	U	Issue No.	24 (cont)	
LM End	0.68	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.991062 °	38.991062 °	
				-121.499886 °	-121.499886 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:50232						
DS_ID:22951						
EP_NO: N/A						
Repair Type: Urgent						
Crossing Status: Found						
UCIP Comments: 06/30/2016 Corrosion still present on WS end. Inlet box was replaced 5 years ago and appears to be functioning properly due to the presence of a screen that prevents debris blockage. Flap gate functions properly only sometimes. WS heavily vegetated. (K. Fazel - UCIP) 03/25/2013 Corrosion holes on WS toe and flap gate is blocked by debris. Flap gate broken. Inlet partially blocked at concrete inlet. (G. Wylie - FPIIB)						
FIELD_STRUCT_DESC: 24-inch corrugated metal gravity drainage pipe through the levee, 20 feet below the crown. Flap gate and headwall on the waterside (WS) end. 56-inch by 34-inch concrete inlet box on the landside (LS) toe. (Due to a recent change in the levee alignment, this pipe is no longer in RD0784, Unit 6. Nevertheless, this pipe's original references remain in the RD0784 Levee Log and O&M Manual).						
[Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 145.1, August 1955, (Station 43+17), As-Built Drawing No. 2-4-106, Sheet 4, (Station 43+17)].						
FS Date: 6/30/2016 9:03:00 AM						

LM Start	0.68	Rating **	U	Issue No.	24 (cont)
LM End	0.68	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_SP_2018_50232_53853.jpg



Holes in pipe at broken flapgate on WS toe.

Photo 3 of 3 : UCIP_SP_2018_50232_53852.jpg



Improvised concrete inlet on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	0.69	Rating **	M	Issue No.	25
LM End	0.69	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.991082 °	38.991082 °
				-121.499888 °	-121.499888 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41163 DS_ID:19020 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to contact CVFPB to comply with Title 23. Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Cleaning of debris on both sides of the levee required. FIELD_STRUCT_DESC: 24-inch corrugated metal drain pipe through the levee, 20.0 feet below the crown. Flap gate on the waterward end. O&M Manual Sac 145, August 1955. FS Date: 4/16/2013					

LM Start	0.69	Rating **	M	Issue No.	25 (cont)
LM End	0.69	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_41163_19942.jpg



WS- CM pipe, flap gate and debris.

Photo 2 of 3 : UCIP_SP_2018_41163_19941.jpg



WS- overview of CM pipe, flap gate and debris.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	0.69	Rating **	M	Issue No.	25 (cont)
LM End	0.69	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.991082 °	38.991082 °
				-121.499888 °	-121.499888 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41163 DS_ID:19020 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to contact CVFPB to comply with Title 23. Dense vegetation on waterward and landward slopes limit visual inspection of potential leaks along pipe alignment. Cleaning of debris on both sides of the levee required. FIELD_STRUCT_DESC: 24-inch corrugated metal drain pipe through the levee, 20.0 feet below the crown. Flap gate on the waterward end. O&M Manual Sac 145, August 1955. FS Date: 4/16/2013					

Photo 3 of 3 : UCIP_SP_2018_41163_19940.jpg



LS- half box concrete outlet structure with trash rack.

LM Start	0.77	Rating **	M	Issue No.	19
LM End	0.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.991879 °	38.991879 °
				-121.498688 °	-121.498688 °
DWR ID	DWR_RD0817_03_f_2016_19				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
Trim tree limbs for access and visibility. Spring 2018.					

Photo 1 of 1 : SP_2018_RD0817_14_19_20180302_00006.jpg



View looking downstream landside of trees that need limbs to be trimmed for access and visibility, Fall 2017.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	0.85	Rating **	M	Issue No.	15
LM End	1.27	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.992669 °	38.996885 °
				-121.497525 °	-121.491956 °
DWR ID	DWR_RD0784_06_s_2013_15				
Comment Code					
FE : Fence					
Inspector Comment					
Wire fence at levee toe.					

Photo 1 of 1 : SP_2018_RD0817_14_15_20180302_00004.jpg



View of fence at landside toe looking downstream.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	1.18	Rating **	U	Issue No.	26
LM End	1.18	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.995852 °	38.995852 °
				-121.493111 °	-121.493111 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:50234
DS_ID:22952
EP_NO: N/A
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: 06/30/2016 Same as last inspection. Good candidate for removal via DWR's Deferred Maintenance Program. Pipe used to drain pastureland which have since been converted to rice fields that drain on opposite side of fields, rendering the drainage function of this pipe obsolete. This pipe is not needed and causes nuisance flooding at high water on landside (LS) per Tom Engler of MBK. As such, operation of flapgate is still blocked via a post at WS end. Pipe is sleeved but sleeve has grossly deteriorated. LS end of pipe appears bent. (K. Fazel - UCIP)03/25/2013 Pipe heavily corroded and damaged. 8-inch PVC pipe runs through pipe/possibly for irrigation. CMP heavily rusted on WS toe and debris blocking flap gate on WS toe. (G. Wylie - FPIIB) FIELD_STRUCT_DESC: *ABANDONED* 20-inch corrugated metal gravity drainage pipe through the levee, 16.5 feet below the crown. 8-inch polyvinyl chloride (PVC) pipe sleeved through the 20-inch corrugated metal pipe with the annular space left void. Flap gate on the waterside (WS) end. (Due to a recent change in the levee alignment, this pipe is no longer in RD0784, Unit 6. Nevertheless, this pipe's original references remain in the RD0784 Levee Log and O&M Manual). [Additional Reference(s): DWR Levee Log, 2005, 24-inch corrugated metal pipe (CMP) referenced. USACE Sacramento O&M Manual 145.1, August 1955, (Station 69+17), 18-inch CMP referenced, As-Built Drawing No. 2-4-106, Sheet 4, (Station 69+17)].
FS Date: 6/30/2016 9:06:00 AM

Photo 1 of 3 : UCIP_SP_2018_50234_53857.jpg



Pipe on LS toe with 8-inch PVC pipe sticking out.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	1.18	Rating **	U	Issue No.	26 (cont)	
LM End	1.18	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.995852 °	38.995852 °	
				-121.493111 °	-121.493111 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:50234 DS_ID:22952 EP_NO: N/A Repair Type: Urgent Crossing Status: Found UCIP Comments: 06/30/2016 Same as last inspection. Good candidate for removal via DWR's Deferred Maintenance Program. Pipe used to drain pastureland which have since been converted to rice fields that drain on opposite side of fields, rendering the drainage function of this pipe obsolete. This pipe is not needed and causes nuisance flooding at high water on landside (LS) per Tom Engler of MBK. As such, operation of flapgate is still blocked via a post at WS end. Pipe is sleeved but sleeve has grossly deteriorated. LS end of pipe appears bent. (K. Fazel - UCIP)03/25/2013 Pipe heavily corroded and damaged. 8-inch PVC pipe runs through pipe/possibly for irrigation. CMP heavily rusted on WS toe and debris blocking flap gate on WS toe. (G. Wylie - FPIIB) FIELD_STRUCT_DESC: *ABANDONED* 20-inch corrugated metal gravity drainage pipe through the levee, 16.5 feet below the crown. 8-inch polyvinyl chloride (PVC) pipe sleeved through the 20-inch corrugated metal pipe with the annular space left void. Flap gate on the waterside (WS) end. (Due to a recent change in the levee alignment, this pipe is no longer in RD0784, Unit 6. Nevertheless, this pipe's original references remain in the RD0784 Levee Log and O&M Manual). [Additional Reference(s): DWR Levee Log, 2005, 24-inch corrugated metal pipe (CMP) referenced. USACE Sacramento O&M Manual 145.1, August 1955, (Station 69+17), 18-inch CMP referenced, As-Built Drawing No. 2-4-106, Sheet 4, (Station 69+17)]. FS Date: 6/30/2016 9:06:00 AM						

Photo 2 of 3 : UCIP_SP_2018_50234_53856.jpg



Pipe cut behind flap gate on WS toe with 8-inch PVC.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	1.18	Rating **	U	Issue No.	26 (cont)	
LM End	1.18	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.995852 °	38.995852 °	
				-121.493111 °	-121.493111 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:50234 DS_ID:22952 EP_NO: N/A Repair Type: Urgent Crossing Status: Found UCIP Comments: 06/30/2016 Same as last inspection. Good candidate for removal via DWR's Deferred Maintenance Program. Pipe used to drain pastureland which have since been converted to rice fields that drain on opposite side of fields, rendering the drainage function of this pipe obsolete. This pipe is not needed and causes nuisance flooding at high water on landside (LS) per Tom Engler of MBK. As such, operation of flapgate is still blocked via a post at WS end. Pipe is sleeved but sleeve has grossly deteriorated. LS end of pipe appears bent. (K. Fazel - UCIP)03/25/2013 Pipe heavily corroded and damaged. 8-inch PVC pipe runs through pipe/possibly for irrigation. CMP heavily rusted on WS toe and debris blocking flap gate on WS toe. (G. Wylie - FPIIB) FIELD_STRUCT_DESC: *ABANDONED* 20-inch corrugated metal gravity drainage pipe through the levee, 16.5 feet below the crown. 8-inch polyvinyl chloride (PVC) pipe sleeved through the 20-inch corrugated metal pipe with the annular space left void. Flap gate on the waterside (WS) end. (Due to a recent change in the levee alignment, this pipe is no longer in RD0784, Unit 6. Nevertheless, this pipe's original references remain in the RD0784 Levee Log and O&M Manual). [Additional Reference(s): DWR Levee Log, 2005, 24-inch corrugated metal pipe (CMP) referenced. USACE Sacramento O&M Manual 145.1, August 1955, (Station 69+17), 18-inch CMP referenced, As-Built Drawing No. 2-4-106, Sheet 4, (Station 69+17)]. FS Date: 6/30/2016 9:06:00 AM						

Photo 3 of 3 : UCIP_SP_2018_50234_53855.jpg



Pipe heavily corroded throughout.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	1.29	Rating **	U	Issue No.	27
LM End	1.29	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.997048 °	38.997048 °
				-121.491743 °	-121.491743 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:50235
DS_ID:22953
EP_NO: N/A
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: 06/30/2016 Sink hole still exists over pipe on LS. LS and WS heavily vegetated and barely accessible. WS end is sleeved with a heavily rusted CMP. Flapgate is clear and functional. (K. Fazel - UCIP)12/17/2015 WS accessible, but LS no longer accessible due to heavy vegetation. (T. Hatch - UCIP)03/25/2013 Pipe visible on LS at toe of roadway embankment, but not visible on WS. Possible sinkhole over pipe at LS toe. Pipe heavily rusted. (G. Wylie - FPIIB)
FIELD_STRUCT_DESC: 18-inch corrugated metal gravity drainage pipe angled through the levee, approximately 15 feet below the crown. Steel pipe sleeved through the 18-inch corrugated metal pipe (CMP) with annular space grouted, grout only on the waterside (WS). Flap gate on the WS end. Pipe alignment is from the west of the intersection of Forty Mile Road and 45 degrees to the WS. Outlet is on the eastern side of Forty Mile Road, looking upstream. (Due to a recent change in the levee alignment, this pipe is no longer in RD0784, Unit 6. Nevertheless, this pipe's original references remain in the RD0784 Levee Log and O&M Manual). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 145.1, August 1955, (Station 74+72), As-Built Drawing No. 2-4-106, Sheet 4, (Station 74+72)].
FS Date: 6/30/2016 9:08:00 AM

LM Start	1.29	Rating **	U	Issue No.	27 (cont)
LM End	1.29	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2018_50235_53859.jpg



Pipe at inlet on LS toe.

Photo 2 of 3 : UCIP_SP_2018_50235_53858.jpg



Sinkhole or animal burrow over pipe on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Reclamation District No. 0817 Carlin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 South Dry Creek	Right	1.32	04/18/2018 04/18/2018	Sterling York

LM Start	1.29	Rating **	U	Issue No.	27 (cont)	
LM End	1.29	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.997048 °	38.997048 °	
				-121.491743 °	-121.491743 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:50235 DS_ID:22953 EP_NO: N/A Repair Type: Urgent Crossing Status: Found UCIP Comments: 06/30/2016 Sink hole still exists over pipe on LS. LS and WS heavily vegetated and barely accessible. WS end is sleeved with a heavily rusted CMP. Flapgate is clear and functional. (K. Fazel - UCIP)12/17/2015 WS accessible, but LS no longer accessible due to heavy vegetation. (T. Hatch - UCIP)03/25/2013 Pipe visible on LS at toe of roadway embankment, but not visible on WS. Possible sinkhole over pipe at LS toe. Pipe heavily rusted. (G. Wylie - FPIIB) FIELD_STRUCT_DESC: 18-inch corrugated metal gravity drainage pipe angled through the levee, approximately 15 feet below the crown. Steel pipe sleeved through the 18-inch corrugated metal pipe (CMP) with annular space grouted, grout only on the waterside (WS). Flap gate on the WS end. Pipe alignment is from the west of the intersection of Forty Mile Road and 45 degrees to the WS. Outlet is on the eastern side of Forty Mile Road, looking upstream. (Due to a recent change in the levee alignment, this pipe is no longer in RD0784, Unit 6. Nevertheless, this pipe's original references remain in the RD0784 Levee Log and O&M Manual). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 145.1, August 1955, (Station 74+72), As-Built Drawing No. 2-4-106, Sheet 4, (Station 74+72)]. FS Date: 6/30/2016 9:08:00 AM						

Photo 3 of 3 : UCIP_SP_2018_50235_74804.jpg



WS drainage outlet with flap gate. Steel pipe is sleeved within heavily rusted CM pipe near daylight to embankment

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---